

SAFETY BULLETIN

Port Kembla

Cargo Matting Storage Bins

Timber dunnage left scattered across the berth after the collection of Excavators and Equipment offers a significant risk to vehicles transiting the Terminal.



AAT have implemented the trial of rubber cargo matting as a replacement for timber dunnage.

The Rubber matting storage boxes will be situated in 3 locations along berth 105/106/107.



Steven Cowley
Safety Operations Superintendent
30 Sept 2016
No: BLTN-PK-018